EXISTING PEDESTRIAN CONDITIONS AND PRIORITY SIDEWALK RECOMMENDATIONS

This map highlights existing pedestrian conditions in Wilmette such as sidewalk gaps, locations of interest, transit, and pedestrian-involved crashes. Based on these conditions and other community feedback, several priority locations for new sidewalks were identrified for consideration.

